


- All dimensions are measured in inches and [millimeters] from the top of the door to the centerline of the holes.
- Dimensions shown inside boxes are frame face mounting screw holes.


**For 83" HD
Model SL41 Swing Clear**

44 fasteners / 32 bearings



**For 83" LL
Model SL41 Swing Clear**

58 fasteners / 32 bearings



TEMPLATES


Swing Clear Geared Hinges



- All dimensions are measured in inches and [millimeters] from the top of the door to the centerline of the holes.
- Dimensions shown inside boxes are frame face mounting screw holes.


For 85" HD Model SL41 Swing Clear

44 fasteners / 32 bearings



For 85" LL Model SL41 Swing Clear


58 fasteners / 32 bearings



- All dimensions are measured in inches and [millimeters] from the top of the door to the centerline of the holes.
- Dimensions shown inside boxes are frame face mounting screw holes.


**For 95" HD
Model SL41 Swing Clear**

48 fasteners / 36 bearings



**For 95" LL
Model SL41 Swing Clear**

66 fasteners / 36 bearings



TEMPLATES

Swing Clear Geared Hinges




- All dimensions are measured in inches and [millimeters] from the top of the door to the centerline of the holes.
- Dimensions shown inside boxes are frame face mounting screw holes.

For 120" HD Model SL41 Swing Clear

52 fasteners / 47 bearings

HOLES **FRAME FACE HOLES**



For 120" LL Model SL41 Swing Clear

74 fasteners / 47 bearings

HOLES **FRAME FACE HOLES**

